







CP2316H3




EAC

CP2316H3




A x12
Spec: $\varnothing 8 \times 30$



B x4
Spec: $\varnothing 7 \times L30$



C x4
Spec: $\varnothing 15 \times H12$



D x4
Spec: $\varnothing 3.5 \times L35$



E x4
Spec: $\varnothing 6 \times L28$



F x4
Spec: $\varnothing 12 \times H9$



G x4
Spec: $\varnothing 6 \times L8$




H x4
Spec: $\varnothing 6 \times L30$





I x1
Spec: 4#



J x4
Spec: $\varnothing 3.5 \times L16$




K x4
Spec: H13




M x1
Spec: L300



N x8
Spec:




O x4
Spec: $\varnothing 60 \times 25$



P x4
Spec: $\varnothing 3.8 \times L32$





AAA x4
Spec: $\varnothing 3.8 \times L12$



1


2






3


4






5


6






7

8





10

