







CPM7049




EAC

CPM7049



A x10
Spec: $\varnothing 8 \times 30$



B x10
Spec: $\varnothing 7 \times L30$



C x10
Spec: $\varnothing 15 \times H12$



D x8
Spec: $\varnothing 6 \times L28$



E x8
Spec: $\varnothing 12 \times H9$




F x8
Spec: $\varnothing 6 \times L9$




G x8
Spec: $\varnothing 3.5 \times L35$




H x8
Spec: $\varnothing 3.5 \times L16$



I x8
Spec: H13




J x2
Spec: L300



K x18
Spec:





AAA x8
Spec: $\varnothing 3.8 \times L12$



1


2






3


4






5


6






7

8





9
