





CPM7051




A x40
Spec: $\phi 8 \times 30$



B x20
Spec: $\phi 7 \times L30$




C x20
Spec: $\phi 15 \times H12$



D x24
Spec: $\phi 6 \times L28$



E x24
Spec: $\phi 12 \times H9$




F x12
Spec: $\phi 3.5 \times L35$



G x39
Spec: $\phi 6 \times 30$




H x18
Spec: $\phi 6 \times L9$



I x3
Spec: L350



J x10
Spec: $\phi 3.5 \times L16$



K x10
Spec: H13




L x44
Spec:




M x5
Spec: $\phi 3.8 \times L25$



N x22
Spec: $3.8 \times L16$




O x6
Spec:



P x3
Spec: L946





AAA x12
Spec: $\phi 3.8 \times L12$



1


2






3


4






5


6






7


8






9


10






11

12





13

14

