






CPM7052




EAC

CPM7052



A x28
Spec: $\varnothing 8 \times 30$



B x20
Spec: $\varnothing 7 \times L30$



C x20
Spec: $\varnothing 15 \times H12$




D x8
Spec: $\varnothing 6 \times L28$



E x8
Spec: $\varnothing 12 \times H9$



F x8
Spec: $\varnothing 6 \times L9$




G x8
Spec: $\varnothing 3.5 \times L35$




H x28
Spec:




I x8
Spec: $\varnothing 6 \times 30$



J x2
Spec: L300



K x4
Spec: M6*35




L x8
Spec: M6*55



M x12
Spec: $\varnothing 8 \times \varnothing 18$





AAA x8
Spec: $\varnothing 3.8 \times L12$



1


2







3

4






5





6



7

8





10

