






CPM7053




EAC

CPM7053




A x40
Spec: $\varnothing 8 \times 30$



B x30
Spec: $\varnothing 7 \times L30$




C x30
Spec: $\varnothing 15 \times H12$



D x12
Spec: $\varnothing 6 \times L28$



E x12
Spec: $\varnothing 12 \times H9$




F x12
Spec: $\varnothing 3.5 \times L35$





G x12
Spec: $\varnothing 6 \times 30$



H x12
Spec: $\varnothing 6 \times L8$



I x3
Spec: L300



J x8
Spec: M6*55



K x4
Spec: M6*35



L x12
Spec: $\varnothing 8 \times \varnothing 14$



M x26
Spec:




N x16
Spec:



O x1
Spec:





AAA x12
Spec: $\varnothing 3.8 \times L12$



1


2






3


4






5

6





7

8

