






CPM7054




EAC

CPM7054




A x24
Spec: $\varnothing 8 \times 30$



B x16
Spec: $\varnothing 7 \times L30$



C x16
Spec: $\varnothing 15 \times H12$




D x3
Spec:



E x6
Spec: $\varnothing 3.5 \times L11$



F x18
Spec: $\varnothing 3.5 \times L16$




G x18
Spec: H13



H x12
Spec: $\varnothing 5 \times L19$



I x12
Spec: $\varnothing 20 \times H12$



J x8
Spec: M6*55



K x4
Spec: M6*35




L x12
Spec: $\varnothing 8 \times \varnothing 14$




M x16
Spec:



N x16
Spec: 3.8*L16




O x4
Spec: 089#



P x2
Spec: 079#





Q x6
Spec: $\varnothing 3.8 \times L25$



1


2






3


4






5

6





7

8

