







CPM7055




EAC

CPM7055



A x4
Spec: $\varnothing 10 \times L40$




B x4
Spec: $M8 \times L95$



C x4
Spec:




D x4
Spec: $M8$



E x1
Spec: 14#



F x4
Spec: $\varnothing 38$



G x8
Spec: $\varnothing 3.8 \times L25$




H x12
Spec: $5/16 \times 25$




I x12
Spec: $\varnothing 18 \times \varnothing 8$




J x1
Spec: 5#



K x8
Spec: $5/16 \times L60$




L x4
Spec: $L275$



M x16
Spec: $M6 \times L45$





N x24
Spec: $\varnothing 8 \times \varnothing 18$



1


2





3

4



5

